

Wessex Light Aeroplane Co. Ltd.

SERVICE BULLETON

TITLE: Correct Routing of Seat Belt Lap Straps.

No: WLACSB-H01.

ISSUE DATE: 16th July 2008


APPLICABLE: All Xair Hawk Aircraft.

DETAILS:

Correct routing of the Seat Belt Lap Straps is important to prevent fowling of the elevator control system.

Belts should be routed behind the seat back diagonal tubes 339050 as shown below and not over the top close to the pulleys.

Some aircraft may have also incorporated a strap to the side of the seat which also helps to keep belts away from control system, so long as routing of the belt complies to this service bulletin.



Signed:

Seamus O'Donnell
Technical Director Wessex LAC